

State Water Resources Control Board

October 28, 2015

(Via email and Certified Mail)

CERTIFIED MAIL

NO. 7015 0640 0006 0950 4261

Mr. Manny Ramirez
Environmental Specialist
Environmental Management Division
The Port of Los Angeles
425 South Palos Verdes Street
San Pedro, California 90731
mramirez@portoflosangeles.org

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEM
LOCATED AT THE PORT OF LOS ANGELES POLICE DEPARTMENT,
330 SOUTH CENTRE STREET, SAN PEDRO**

Dear Mr. Ramirez:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on October 8, 2015, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Operating Permit – The facility permit to operate is expired.	Diesel	October 8, 2015	Ongoing	H&SC 25284(a)
2	Failure to Submit or Update Facility and Tank Information (A & B Forms) – The tank information form in CERS contains errors and needs to be updated to include the type of corrosion protection. The facility information form should not include details about being located on an Indian reservation.	Diesel	October 8, 2015	Ongoing	H&SC 25286(a); 23 CCR 2711(a)
3	Failure to Maintain Monitoring Plan – The monitoring plan should indicate that an automatic tank gauge (ATG) is in use.	Diesel	October 8, 2015	Ongoing	H&SC 25286(a); 23 CCR 2632(d)(1), 2634(a),(b),(c) & (d), 2711(a)(9)

No.	Violation	Tank	Start Date	Stop Date	Regulation
4	Failure to Maintain Evidence of Financial Responsibility Onsite – The CFO letter was not available at the time of inspection.	Diesel	October 8, 2015	Ongoing	23 CCR 2712(i)
5	Failure to Submit or Update Plot Plan/Site Map – The site map does not show sufficient detail, it was not accepted in CERS by the CUPA because it was missing ATG sensors, red jacket mechanical line leak detectors, the building/structure, and a cardinal direction.	Diesel	October 8, 2015	Ongoing	23 CCR 2711(a)(8)
6	Failure to Maintain Line Leak Detectors – Two line leak detectors are installed on the turbines in the piping sump. It must be confirmed that they have the ability to detect a 3 gallon per hour leak and are alternating in operation. Observations during the inspection indicated that both turbines and line leak detectors were in operation at the same time.	Diesel	October 8, 2015	Ongoing	23 CCR 2636(f)(2)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Los Angeles City Fire Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Ms. Rebecca Green
 UST Enforcement Unit
 State Water Resources Control Board
 1001 I Street, 16th Floor
 Sacramento, California 95814
rebecca.green@waterboards.ca.gov

Local CUPA

Mr. Aaron Mungaray
 Fire Inspector I
 Los Angeles City Fire Department
 200 Main Street, Suite 1700
 Los Angeles, California 90012
aaron.mungaray@lacity.org

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: *(via email only)*

Ms. Anna Olekszyk
Acting CUPA Manager
Los Angeles City Fire Department
anna.olekszyk@lacity.org

Captain Daniel Dragotto
Los Angeles City Fire Department
daniel.dragotto@lacity.org

Mr. Aaron Mungaray
Fire Inspector I
Los Angeles City Fire Department
aaron.mungaray@lacity.org

Mr. Wayne Mukogawa
Senior Building Operating Engineer
Construction & Maintenance, Customs & Border Patrol
Port of Los Angeles
wmukogawa@portla.org

Mr. Tabb Bubier, Principal
Pacific Edge Engineering, Inc.
tbubier@pacifedge-eng.com